

# **Triax A/S**

## **TDX/TDH800 Release**

### **4.6.1.39534**

---

#### **SUMMARY**

**Release description of TDX and TDH800 software release**

---

## Table of Content

<b>Table of Content.....</b>	<b>2</b>
<b>1 Introduction.....</b>	<b>3</b>
<b>2 Requirements .....</b>	<b>3</b>
<b>3 New features .....</b>	<b>3</b>
<b>3.1 TDH800 .....</b>	<b>3</b>
<b>3.1.1 DVB-T/T2 frontend.....</b>	<b>3</b>
<b>4 Bug fixes .....</b>	<b>3</b>

## ***TDX & TDH800 Public Release description***

### **1 Introduction**

**Purpose of this document is in short to describe features delivered in the software version it refers to.**

### **2 Requirements**

**This release supports all TDX and TDH800 hardware, except prerelease modules shipped without serial number (before 2010-12-08).**

### **3 New features**

**List of new features added in release 4.6.1.39543, since last release 4.5.1.39324.**

#### **3.1 TDH800**

##### **3.1.1 DVB-T/T2 frontend**

**It is now possible to use PLP for DVB-T2 frontends in the TDH800 system.**

### **4 Bug fixes**

**List of bug fixes corrected in release 4.6.1.39534, since last release 4.5.1.39324.**

**No bug fixes for this release**