

TRIAX A/S

TDX/TDH800 Release

4.7.1.39843

SUMMARY

Release description of TDX and TDH800 software release

Table of Content

Table of Content.....	2
1 Introduction.....	3
2 Requirements	3
3 New features	3
3.1 TDH800	3
3.1.1 DVB-C frontend:.....	3
4 Bug fixes	3
4.1 General:.....	3
4.2 Frontend's:	3

TDX & TDH800 Public Release description

1 Introduction

Purpose of this document is in short to describe features delivered in the software version it refers to.

2 Requirements

This release supports all TDX and TDH800 hardware, except prerelease modules shipped without serial number (before 2010-12-08).

3 New features

List of new features added in release 4.7.1.39843, since last release 4.6.1.39534.

3.1 TDH800

3.1.1 DVB-C frontend:

New DVB-C frontend type 692824 now supported in the TDH800 system.

4 Bug fixes

List of bug fixes corrected in release 4.7.1.39843, since last release 4.6.1.39534.

4.1 General:

- **Set manual SDT version number is not effected at the output.**

4.2 Frontend's:

- **If a frontend blocks the I2C then are all frontends restarted. Now is only the error effected FE restarted**