

Triax A/S

TDX/TDH800 Release

4.4.1.39167

SUMMARY

Release description of TDX and TDH800 software release



TRIAX

Table of Content

Table of Content.....	2
1 Introduction.....	3
2 Requirements	3
3 New features	3
3.1 IP out at AUX:	3
4 Bug fixes	4



TRIAX

TDX & TDH800 Public Release description

1 Introduction

Purpose of this document is in short to describe features delivered in the software version it refers to.

2 Requirements

This release supports all TDX and TDH800 hardware, except prerelease modules shipped without serial number (before 2010-12-08).

3 New features

List of new features added in release 4.4.1.39167, since last release 4.3.1.39054.

3.1 IP out at AUX:

It is now possible to set the ONID and TSID at IP-out at AUX (from IP BE). Before was the values fixed for ONID and TSID. ONID was 0xABBA (43962) and TSID was 0x00 (0).

The default values for the ONID, TSID and SID is now the origin from the input. Already configured IP-outs will keep the values given at the configuration time, so making a SW update to this version will not change the ONID and TSID but keep the old setting.

SELECT SERVICES

Services	Types	SID	Service sources	Select service(s)	Output SID	TSID	ONID
3sat HD	HDTV	11150	(Main Unit, input 8)	<input checked="" type="checkbox"/>	38	0	43962
ATV HD	HDTV	\$ 13228	(Main Unit, input 5)	<input type="checkbox"/>	13228	1003	1
ATV2	TV	\$ 13223	(Main Unit, input 5)	<input type="checkbox"/>	13223	1003	1
ATV2_descrambled	TV	13223	(Main Unit, cam 1-A)	<input type="checkbox"/>	13223	1003	1
ATVsmart	TV	13230	(Main Unit, input 5)	<input type="checkbox"/>	13230	1003	1
AV 1	TV	1	(Main Unit, input 14)	<input type="checkbox"/>	1	1	0
Bibel TV HD	HDTV	13224	(Main Unit, input 5)	<input type="checkbox"/>	13224	1003	1
BR Fernsehen Nord	TV	28110	(Unit 1, input 5)	<input type="checkbox"/>	28110	1101	1
BR Fernsehen Nord HD	HDTV	10326	(Unit 1, input 3)	<input type="checkbox"/>	10326	1025	1

Currently active elementary streams

Services	Stream type	Details	Original PID	Select PID(s)	Conflict	Output PID
3sat HD	PMT		6500	<input checked="" type="checkbox"/>		6500
3sat HD	H264 Video (PCR)		6510	<input checked="" type="checkbox"/>		6510
3sat HD	Audio	DEU	6520	<input checked="" type="checkbox"/>		6520
3sat HD	Audio	MIS	6521	<input checked="" type="checkbox"/>		6521

STATUS INFORMATION
Status: OK; SW-Revision: 4.4.1.39167; Interface IP address: 192.168.30.3;



TRIAX

TDX & TDH800 Public Release description

4 Bug fixes

List of bug fixes corrected in release 4.4.1.39167, since last release 4.3.1.39054.

No bug fixes